



# Acer Aspire V5-572, V5-572G CMOS Battery Replacement

Acer Aspire V5-572,V5-572G CMOS Battery Replacement

Written By: ZFix



## INTRODUCTION

Acer Aspire - V5-572, V5-572G

If the Laptop shows sometimes error messages related to time and date options or CMOS checksum error, you must to change the battery of the motherboard.

This guide will show you how to do this.

[Please SUBSCRIBE to my channel ツ](#)

[video: <http://youtu.be/Sg8tUXZL864>]



### TOOLS:


- [Phillips #0 Screwdriver](#) (1)
- [iFixit Opening Tools](#) (1)
- [iFixit Opening Picks set of 6](#) (1)



### PARTS:



- [CR2032 Lithium Battery](#) (1)

## Step 1 — Bottom Cover




- Switch-off the Laptop.
- Remove 17x Philips screws.

## Step 2



- Start opening from the SD Memory Card hole
- ⚠ Use plastic tools to avoid damaging the cover.


## Step 3



⚠ Before doing anything, disconnect the battery.

★ [Please SUBSCRIBE to my channel](#)  
[ツ](#)

## Step 4 — CMOS BIOS Battery



- Lithium Battery tape CR 2032, 3V
- [Please SUBSCRIBE to my channel](#)  
[ツ](#)

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-21 06:55:53 PM.